


Welding male BSP 60° union

| Part n° | DN | R1 | L | L1 | ØC | ØD |
|----------------|-------|-----------|----|----|------|-----|
| Z129002 | 1/8" | 1/8" BSP | 24 | 11 | 10 | 3,5 |
| Z129004 | 1/4" | 1/4" BSP | 25 | 12 | 13 | 6 |
| Z129006 | 3/8" | 3/8" BSP | 27 | 15 | 16,5 | 8 |
| Z129008 | 1/2" | 1/2" BSP | 35 | 17 | 21 | 12 |
| Z129012 | 3/4" | 3/4" BSP | 41 | 20 | 26,5 | 15 |
| Z129016 | 1" | 1" BSP | 50 | 21 | 33 | 20 |
| Z129020 | 1"1/4 | 1"1/4 BSP | 52 | 24 | 42 | 30 |
| Z129024 | 1"1/2 | 1"1/2 BSP | 57 | 26 | 48 | 37 |
| Z129032 | 2" | 2" BSP | 60 | 28 | 59,5 | 45 |