

Product Information Bulletin

PIB: PV2011-001

Date: February 24, 2011

PRODUCTS AFFECTED:
PVG32, PVG100, PVG120

SUBJECT:
PVM base/lever design change and variant reduction
Update to PIB PV2009-007

MODELS AFFECTED:

155G3040, -3041, -3050, -3051

157B3151, -3152, -3154, -3155, -3161, -3162, -3163, -3164, -3165, -3171, -3172, -3174, -3175, -3184, -3191, -3192, -3194 -3195

155L3151, -3154, -3450, -3451

Component	PVM base and handle
Modified	New design of base and handle; Reduction of PVM variants; Spare part kit 11077262 added in update. Caution rephrased.
Date of introduction	January 2010 – March 2010; see also page 4

New design of base and handle of PVM

To further improve the strength of the mechanical actuation, a design change is implemented, and as a consequence of this, handle and base have been re-designed.

The new design will ease mounting of handle and base on shaft.

New design will replace 37.5 and 22.5 degree versions into a common design (see also page 5).

